EXAMPLE OF TIMELINES AND TRIGGERS

Parameter	wx sensor status (inop/operable)	Criteria (Occuring or Forecasted)	Observer Backup Recall Requirement	Maintenance backup Recall Requirement	Trigger		
Ceiling (CIG)	inop	No CIG or CIG >= 5,000	4 hr telephone standby	maintainer recalled	OWS		
	inop	Ceiling < 5,000	2-hr telephone standby	maintainer recalled	OWS		
	inop	Ceiling < 2,000	1 hour telephone Standby	maintainer recalled	OWS/TWR		
	inop	Ceiling < 1,000	Onsite Backup	maintainer recalled	OWS/TWR		
Visibility (VIS)	inop	VIS > 7 SM	4 hr telephone standby	maintainer recalled	OWS		
	inop	VIS > 3 SM	2-hr telephone standby	maintainer recalled	OWS		
	inop	VIS <= 2 SM but >1 SM	1/2 hour telephone Standby	maintainer recalled	OWS/TWR		
	inop	VIS <= 1 SM	Onsite Backup	maintainer recalled	OWS/TWR		